

Sta. of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Data: Soutember 20, 2006

Supervisor TH

Report Date: September 29, 2006

Mine Name: Rhyolite 1 Operator Name: Color Country Rock Preston Hafen 115 South Main Veyo, Utah 84782 Inspector(s): Doug Jensen Other Participants: None Mine Status: Inactive	Permit number: Date: September Time: 4:30 PM Weather: Clear	
Elements of Inspection 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other Purpose of Inspection: Inspected the site while I was in the area.	Evaluated Con	nment Enforcement
Directions to Site: See previous inspection report. Inspection Summary: There have been no changes to this site since I inspected it. The piles of materials remain the same as they were several years ago. The site is stable with no environmental concerns. Conclusions and Recommendations:		
I will continue to monitor the site when I am in the Inspector's Signature		9/29/06

O:\M021-Iron\S0210032-RhyoliteQuarry\inspections\09142006insp.doc

Ed Ginouves, BLM, Cedar City FO UTU-79327

Color Country Rock

cc: